

APC Smart-UPS SC 1000

Written by WebAdmin

Tuesday, 20 February 2018 04:46 - Last Updated Tuesday, 20 February 2018 04:56

PUSAT SERVICE UPS - semua merk dan tipe (bergaransi)



Kerusakan / keluhan : Mati total / tidak hidup

Kerusakan umum : Mati, nyala lalu mati, Bunyi terus menerus, tidak bisa charge, tidak backup saat listrik mati, Blinking saat dinyalakan, lampu panel kedap-kedip, Charging tidak bisa penuh

Manufacture part number :

SC1000I

Power :

APC Smart-UPS SC 1000

Written by WebAdmin

Tuesday, 20 February 2018 04:46 - Last Updated Tuesday, 20 February 2018 04:56

1000VA, Input AC 230V / Output 230V 5% (50/60Hz)

Connectors :

Input 1 x power IEC 320 EN 60320 C14

Output 4 x power IEC 320 EN 60320 C13

1 x management - RS-232 9 pin D-Sub (DB-9)